

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/07/2011

FORM APPROVED

OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15E594		(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED 03/22/2011	
NAME OF PROVIDER OR SUPPLIER  MCGIVNEY HEALTH CARE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 2907 EAST 136TH STREET CARMEL, IN46033			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0000	<p>A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 03/22/11</p> <p>Facility Number: 000545 Provider Number: 15E594 AIM Number: 100267350</p> <p>Surveyor: Mark Caraher, Life Safety Code Specialist</p> <p>At this Life Safety Code survey, McGivney Health Care Center was found not in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 Edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.</p> <p>This one story facility with a lower level was determined to be of Type V (111) construction and fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors, areas open to the corridor and in all resident rooms. The facility has a capacity of 37 and had a census of 26 at the time of this</p>			K0000			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/07/2011

FORM APPROVED

OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15E594		X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		X3) DATE SURVEY COMPLETED 03/22/2011	
NAME OF PROVIDER OR SUPPLIER  MCGIVNEY HEALTH CARE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 2907 EAST 136TH STREET CARMEL, IN46033			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PERCEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0039 SS=D	<p>visit.</p> <p>Quality Review by Robert Booher, REHS, Life Safety Code Specialist-Medical Surveyor on 03/22/11.</p> <p>The facility was found not in compliance with the aforementioned regulatory requirements as evidenced by the following:</p> <p>Based on observation and interview, the facility failed to ensure 1 of 3 exit access corridors had an exit width of at least 4 feet (48 inches). This deficient practice could affect 3 of 26 residents using the west corridor.</p> <p>Findings include:</p> <p>Based on observation with the Administrator during the tour of the facility from 11:10 a.m. to 12:45 p.m., the exit access corridor serving resident room 5 measured thirty eight inches in width. Based on interview at the time of observation, the Administrator acknowledged the exit access corridor serving resident room 5 is less than four feet in width.</p>			K0039	<p>K 039We are requesting a waiver for the size of the exit access corridor as it meets the needs of the residents and it does not create a hazard to the safety of our residents. Please see enclosed letter and Life Safety Code Waiver Request.Gibault Care Inc., is responsible for the finding.</p>		04/21/2011

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/07/2011

FORM APPROVED

OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15E594		X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		X3) DATE SURVEY COMPLETED 03/22/2011	
NAME OF PROVIDER OR SUPPLIER  MCGIVNEY HEALTH CARE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 2907 EAST 136TH STREET CARMEL, IN46033			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PERCEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	3.1-19(b)						